


# STORMWATER OUTFALL PIPE STREAM SCOUR INSPECTION

# TOWNSHIP OF ROCHELLE PARK



Township of Rochelle Park

Rochelle Park, New Jersey

PROJECT NAME: Stormwater Outfall Survey PROJECT No.: ROP-153

# Photo No. 1.

# Description:

Discharge ID: D-1

Location:

30 Lakeview Ave

Watercourse:

Sprout Brook

Size:

18" RCP

Condition:

Excellent

Scour: No

**Illicit Connection:** 

Repair:

Install Headwall

Owner: Municipal



# Photo No. 2.

# Description:

Discharge ID: D-2

Location:

150 West Passaic St

Watercourse:

Sprout Brook

Size:

24" RCP

Condition:

Good

Scour:

Illicit Connection:

No

Repair:

No



### SITE PHOTOGRAPHS

Township of Rochelle Park

SITE LOCATION:

Rochelle Park, New Jersey

PROJECT NAME:

Stormwater Outfall Survey

PROJECT No.: ROP-153

# Photo No. 3.

# Description:

Discharge ID: D-3

Location:

120 West Passaic St

Watercourse:

Sprout Brook

Size:

24" RCP

Condition:

Good

Scour:

No

Illicit Connection:

Repair:

No

Owner: County



# Photo No. 4.

# Description:

Discharge ID:

D-4

Location:

151 West Passaic St

Watercourse:

Sprout Brook

Size:

15" RCP

Condition:

Poor

Scour:

Yes

Illicit Connection:

No

Repair:

Repair Headwall and Install Conduit Outlet Protection

**NJDEP Permit Required** 



IENT NAME: SITE LOCATION:

Township of Rochelle Park Rochelle Park, New Jersey

PROJECT NAME: Stormwater Outfall Survey PROJECT No.: ROP-153

# Photo No. 5.

# Description:

Discharge ID: D-5

### Location:

32 Schlosser Dr (Approx.)

### Watercourse:

Sprout Brook

### Size:

18" HDPE

### Condition:

Good

### Scour:

No

### **Illicit Connection:**

No

### Repair:

Install Headwall and Conduit Outlet Protection NJDEP Permit Required

Owner: Municipal



### Photo No. 6.

# Description:

Discharge ID:

D-6

### Location:

161 West Passaic St

### Watercourse:

Sprout Brook

### Size:

18" RCP

### Condition:

Excellent

### Scour:

Νo

### Illicit Connection:

No

### Repair:

No

Owner: Private



### SITE PHOTOGRAPHS

Township of Rochelle Park

SITE LOCATION:

Rochelle Park, New Jersey

PROJECT NAME:

Stormwater Outfall Survey

PROJECT No.: ROP-153

# Photo No. 7.

# Description:

Discharge ID: D-7

Location:

201 West Passaic St

Watercourse:

Sprout Brook

18" Elliptical RCP

Condition:

Poor

Scour:

Yes

**Illicit Connection:** 

Repair: Install Conduit Outlet Protection

**NJDEP Permit Required** 

Owner: Private



### Photo No. 8.

# Description:

Discharge ID:

D-8

Location:

235 West Passaic St

Watercourse:

Sprout Brook

Size:

18" RCP

Condition:

Good

Scour:

Yes

Illicit Connection:

No

Repair:

Install Headwall and Conduit Outlet Protection

NJDEP Permit Required

Owner: Private



### SITE PHOTOGRAPHS

Township of Rochelle Park Rochelle Park, New Jersey PROJECT NAME:

Stormwater Outfall Survey

PROJECT No.: ROP-153

# Photo No. 9.

# Description:

Discharge ID: D-9

Location:

21 Hobart Ct

Watercourse:

Sprout Brook

Size:

15" RCP

Condition:

Excellent

Scour:

No

**Illicit Connection:** 

Repair:

No

Owner: Municipal



# Photo No. 10.

# Description:

Discharge ID: D-10

Location:

21 Hobart Ct

Watercourse:

Sprout Brook

Size:

36" CMP

Condition:

Excellent

Scour:

Illicit Connection:

No

Repair:

No



### SITE PHOTOGRAPHS

Township of Rochelle Park

SITE LOCATION:

Rochelle Park, New Jersey

PROJECT NAME: Stormwater Outfall Survey PROJECT No.: ROP-153

# Photo No. 11.

# Description:

Discharge ID: D-11

Location:

91 South Dr

Watercourse:

Sprout Brook

Size:

18" RCP

Condition:

Good

Scour:

Yes

**Illicit Connection:** 

Repair:

Install Headwall and Conduit Outlet Protection **NJDEP Permit Required** 

Owner: Municipal



# Photo No. 12.

# Description:

Discharge ID:

D-12

Location:

171 Chestnut St

Watercourse:

Sprout Brook

Size:

18" RCP

Condition:

Good

Scour:

Yes

Illicit Connection:

No

Repair:

Install Conduit Outlet Protection

**NJDEP Permit Required** 



### SITE PHOTOGRAPHS

CLIENT NAME:

Township of Rochelle Park

SITE LOCATION:

Rochelle Park, New Jersey

PROJECT NAME:

Stormwater Outfall Survey

PROJECT No.:

ROP-153

# Photo No. 13.

# Description:

Discharge ID: D-13

Location:

158 Forest Pl

Watercourse:

Sprout Brook

Size:

15" RCP

Condition:

Fair

Scour:

No

**Illicit Connection:** 

No

Repair:

Install Headwall and Conduit Outlet Protection NJDEP Permit Required

Owner: Private



# Photo No. 14.

# Description:

Discharge ID: D-14

Location:

145 Forest Pl

Watercourse:

Sprout Brook

Size:

18" RCP

Condition:

Fair

Scour:

Yes

Illicit Connection:

Investigate

Repair:

Install Conduit Outlet Protection

NJDEP Permit Required



### SITE PHOTOGRAPHS

Township of Rochelle Park

SITE LOCATION:

Rochelle Park, New Jersey

PROJECT NAME:

Stormwater Outfall Survey

PROJECT No.: ROP-153

# Photo No. 15.

# Description:

Discharge ID: D-15

### Location:

395 West Passaic St

### Watercourse:

Saddle River

### Size:

24" RCP

### Condition:

Excellent

### Scour:


No

### Illicit Connection:

### Repair:

No

Owner: Private



# Photo No. 16.

# Description:

Discharge ID:

D-16

<u>Location:</u> Saddle River County Park

### Watercourse:

Saddle River

### Size:

24" CMP

### Condition:

Fair

### Scour:

Yes

### Illicit Connection:

No

### Repair:

Install Headwall and Conduit Outlet Protection

### **NJDEP Permit Required**



Township of Rochelle Park Rochelle Park, New Jersey PROJECT NAME: Stormwater Outfall Survey PROJECT No.: ROP-153

# Photo No. 17.

Description:

Discharge ID: D-17

Location:

23 Brooks Ave

Watercourse:

Saddle River

Size:

Unknown

Condition:

Unknown

Scour:

Unknown

Illicit Connection:

Unknown

Repair:

Locate Pipe and Reevaluate

Owner: Municipal



# Photo No. 18.

# Description:

Discharge ID:

D-18

Location:

151 West Passaic St

Watercourse:

Saddle River

Size:

42" RCP

Condition:

Excellent

Scour:

Illicit Connection:

No

Repair:

No



### SITE PHOTOGRAPHS

SITE LOCATION: CLIENT NAME: Township of Rochelle Park Rochelle Park, New Jersey PROJECT NAME: Stormwater Outfall Survey PROJECT No.: ROP-153

# Photo No. 19.

# Description:

Discharge ID: D-19

Location:

Railroad Ave

Watercourse:

Saddle River

Size:

18" RCP

Condition:

Good

Scour:

No

**Illicit Connection:** 

Repair:

No

Owner: County



# Photo No. 20.

# Description:

Discharge ID:

D-20

Location:

Railroad Ave

Watercourse:

Saddle River

Size:

15" RCP

Condition:

Good

Scour:

Illicit Connection:

No

Repair:

Install Flared End Section NJDEP Permit Required



CLIENT NAME: Township of Rochelle Park

Rochelle Park, New Jersey

PROJECT NAME: Stormwater Outfall Survey PROJECT No.: ROP-153

# Photo No. 21.

# Description:

Discharge ID: D-21

Location:

22 Becker Ave

Watercourse:

Westerly Branch

Size:

15" RCP

Condition:

Good

Scour: No

**Illicit Connection:** 

Repair:

No

Owner: Municipal



# Photo No. 22.

# Description:

Discharge ID:

D-22

Location:

Becker Ave

Watercourse:

Westerly Branch

15" RCP

Condition:

Good

Scour:

Illicit Connection:

No

Repair:

No



CLIENT NAME:

Township of Rochelle Park

SITE LOCATION:

Rochelle Park, New Jersey

PROJECT NAME:

Stormwater Outfall Survey

PROJECT No.: ROP-153

# Photo No. 23.

# Description:

Discharge ID: D-23

Location:

Becker Ave

Watercourse:

Westerly Branch

<u>Size:</u> 42" RCP

Condition:

Good

Scour:

No

**Illicit Connection:** 

Repair:

No

Owner: Municipal



# Photo No. 24.

# Description:

Discharge ID: D-24

<u>Location:</u> 91 Rochelle Ave

Watercourse:

Westerly Branch

4'x3' Box Culvert

Condition:

Excellent

Scour:

Illicit Connection:

No

Repair:

No



### **SITE PHOTOGRAPHS**

CLIENT NAME: SITE LOCATION: PROJECT NAME: Rochelle Park, New Jersey Township of Rochelle Park

Stormwater Outfall Survey

PROJECT No.: ROP-153

# Photo No. 25.

# Description:

Discharge ID: D-25

### Location:

12 Rochelle Ave

### Watercourse:

Saddle River

Size:

12" RCP

Condition:

Good

Scour:

No

**Illicit Connection:** 

No

Repair:

No



